Annexure C

PROFORMA FOR SAFE DRINKING WATER AND SANITARY CONDITION CERTIFICATE

PROF CHAIR 1
No. Dated:
No. It is certified that an inspection team headed by Mr. Rajesh Kumar (Name of Officers with designation) from Engineer) PHED
(Name of Officers with designation) from
inspected the MHD WORLD SCHOOUL
24/07/12 (date of inspection) and on the basis of
Water Test Report (Attached) bearing no
of Hastha Health Carl (PHED Lab) Certified with
the MHD WORLD SCHOOL (Name of school) has safe drinking water
facilities for the students and members of staff of the institution. School is also maintains the
hygienic sanitation condition in the school building & the campus as per norms prescribed by the
Central/ State/ U.T. Govt. Por Aastha Health Gare Froducts
This certificate is valid till Up to 1 Year
This certificate is valid till Up to 1 Year Prop. 24/07/26 Signature with Seal: Mr. Rayesh Kumare Name Designation Engineer Name & Address of the Office Department: Aasth a
Designation : Engineer
To a al 1 Medical Health Call
MHD WORLD SCHOOL, NANUANA Swatgaria Bazaar, Sins
(Name & Address of the Institution)
Note: The certificate is to be issued by authorized officer / PHED Lab / local bodies

67 | Page



Cell.: 92541-50746 94664-71888

Aastha Healthcare Products

Jaat Dharamshala, Old Bus Stand, Sirsa - 125055 (Hry.)

Deals in : R.O. Plant, Inverter Battery, Gas Geyser, Solar Pannel etc.

Ref. No. AHP. 25. 90...

Dated 25 / 07 / 25

WATER QUALITY CHECKUP CERTIFICATE

This is to certify that on 24 July 2025, a comprehensive water quality checkup was conducted at MHD World School, Nanuana, Covering all the School Campus. The inspection included testing of drinking water sources for physical, chemical, and microbiological parameters to ensure compliance with safety and hygiene standards. Upon thorough examination, the water was found to be safe, clean, and suitable for drinking and general use across all specified floors.

This certificate is issued for official use and record purposes.

Date of Inspection: 24-07-2025

Location: MHD World School, Nanuana

Campus – Ground Floor, First Floor

Status: Water quality check completed and found satisfactory